



Above: The kitchen fulfilled the owner's desire for a grand and sophisticated room outfitted with furniture-quality cabinets abundant in architectural detail and time-seasoned character.
Photograph by Mike Jensen Photography



Facing Page Left: A sensitive remodel redeemed a classic Craftsman home previously targeted to be torn down. By cleaning up several previous haphazard remodeling projects and adding a wraparound veranda with a new trussed-gable entry porch, the home's character was restored and its unrealized potential was finally fulfilled.
Photograph by Northlight Photography Inc.



Facing Page Right: The arrangement of architectural details and interior appointments manages to engage guests in an intimate way that is surprising in such a large entry foyer. The soaring space is capped with a dramatic skylight and flanked by a split stair, adorned with custom metal railings and richly paneled wainscoting.
Photograph by Mike Jensen Photography



Left: Casually sophisticated interior spaces are suffused with light and warmth year round.
Photograph by Phillip Clayton Thomas